



**FORETRAVEL**  
MOTOR COACH

## **IMPORTANT SAFETY RECALL NOTICE**

**17V098**

This notice applies to the vehicle identification number below

---

Dear Foretravel Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety act.

Foretravel Inc. has decided that a defect which relates to motor vehicle safety exist in certain Foretravel Realm motorhomes manufactured by Foretravel from April 04, 2014 to October 31, 2016 equipped with Adjustable Brake Pedal assemblies.

Please note: The Vehicle Identification Number that may be affected by this recall is located at the top of this letter.

### **What is the defect?**

Foretravel discovered there is a possibility of the travel of the brake pedal being restricted when pedal assembly is in the fully forward position not allowing full pedal travel which could result in an accident causing injury or death.

### **Corrective Action**

Your Foretravel dealer will inspect, and if restricted by pedal box will reposition or modify pedal box per the service bulletin procedure.

**Please note:** the service will be provided at no cost to you, the vehicle owner.

### **What Should You Do**

Please contact Foretravel Inc. at 1-800-955-6226, opt 3, to locate a qualified service center near you. Steps will be taken to ensure the recall is performed at the nearest service center.

### **Reimbursement**

The labor time necessary to perform this service correction is approximately .5 hour for check and 1.5 hour if repairs made. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy

of the problem associated with this recall. For more information contact Foretravel Inc., at 1-800-955-6226, opt. 3.


### **Reply Card**

The enclosed owner reply card identifies your vehicle. Presentation of this card to the service center will assist in making the necessary correction in the shortest possible time. If you have sold or traded the vehicle, please let us know by completing the postage paid reply card and returning it to us.

If the authorized service center has failed or is unable to remedy the defect without charge and within a reasonable time, contact Foretravel Inc. at 1-800-955-6226, opt. 3. If you are still not able to have the safety defect remedied without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, D.C. 20590 or call the Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://v.rww.safecar.gov> if you feel the manufacture has failed or is unable to remedy the defect without charge.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely;



*James Triana*

Warranty Director/Customer Assistance  
Foretravel, Inc.